ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0473, W0442, W0458	NA, Own Use Rd	sahakaranagara and tata nagara
Segment No.	**Total Length (m)**	
8/C-W0473/S010555	115.19	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	115.19	77.575693	13.049817	77.576056	13.050779	RI-S62	W0442

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drain at sahakaranagara and tata nagara areas in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	3000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to roads and drain at sahakaranagara and tata nagara areas in Ward no 8 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone	008-15-000030
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/WO/55/2014-15	28/04/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
28/04/2015	27/04/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
P VIJAYA BABU		0.00
Phone No.	**E-Mail ID**	
9845025446		

Field Inspection Details

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0473, W0442, W0458

Number of Trees	Any Other Information	Name
6		SRINIVASA MURTHY

Date of Inspection	Remarks
02/09/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	8	Ward Name:	Kodigehalli	Street ID:	W0473, W0442, W0458

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	02/09/2016	02/10/2016	COMPLETED
SE	VASU K M	02/09/2016	02/10/2016	COMPLETED
EE	YARAPPA REDDY	02/09/2016	02/10/2016	COMPLETED
AEE	RAJANIKANTH	02/09/2016	02/10/2016	COMPLETED
AE	SRINIVASA MURTHY	02/09/2016	02/10/2016	COMPLETED
AE	SRINIVASA MURTHY	02/09/2016	02/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0473, W0442, W0458